

EPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies

810609 MI #95 MIS-000-001-038

A Person Required to Notify:

Enter the name and address of the person or organization required to notify

Name Chrysler Corporation - Chemical Division
Street 5437 W. Jefferson
City Trenton State MI Zip Code 48183

B Site Location:

Enter the common name (if known) and actual location of the site

Name of Site Chrysler Corporation - Chemical Division
Street 5437 W. Jefferson
City Trenton County Wayne State MI Zip Code 48183

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form

Name (Last, First and Title) Robert Campbell - Mfg. Engineering Mgr.
Phone (313) 671-4728

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site

From (Year) 1948 To (Year) Present 1981

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item 1—Description of Site

General Type of Waste.
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category

- 1 ☒ Organics
- 2 ☒ Inorganics
- 3 ☒ Solvents
- 4 ☐ Pesticides
- 5 ☐ Heavy metals
- 6 ☐ Acids
- 7 ☐ Bases
- 8 ☐ PCBs
- 9 ☐ Mixed Municipal Waste
- 10 ☐ Unknown
- 11 ☐ Other (Specify)

Source of Waste.
Place an X in the appropriate boxes

- 1 ☐ Mining
- 2 ☐ Construction
- 3 ☐ Textiles
- 4 ☐ Fertilizer
- 5 ☐ Paper/Printing
- 6 ☐ Leather Tanning
- 7 ☐ Iron/Steel Foundry
- 8 ☒ Chemical, General
- 9 ☐ Plating/Polishing
- 10 ☐ Military/Ammunition
- 11 ☐ Electrical Conductors
- 12 ☐ Transformers
- 13 ☐ Utility Companies
- 14 ☐ Sanitary/Refuse
- 15 ☐ Photofinish
- 16 ☐ Lab/Hospital
- 17 ☐ Unknown
- 18 ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261)

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located

000523 JUN -981

Form Approved
GSA Gen. Reg. No. 27

US EPA RECORDS CENTER REGION 5



409630

JUN 10 1981

Notification of Hazardous Waste Site

Side Two

F Waste Quantity

Place an X in the appropriate boxes to indicate the facility types found at the site

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres

Facility Type

- 1 ☐ Piles
 2 ☐ Land Treatment
 3 ☒ Landfill
 4 ☐ Tanks
 5 ☐ Impoundment
 6 ☐ Underground Injection
 7 ☐ Drums, Above Ground
 8 ☐ Drums, Below Ground
 9 ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet ? See Part I below

gallons _____

Total Facility Area

square feet 18,500

acres _____

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location

Attached

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions

The landfills in question were generated over 15 years ago. Their contents are unknown but based on the products manufactured during the 1948-65 period, there is a possibility that some organic type solvent based adhesives could be contained in the landfills.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other"

Name Robert A. Campbell-Mfg. Engrg. Mgr.


Street 5437 W. Jefferson

City Trenton State MI Zip Code 48183

Signature R.A. Campbell Date 5/27/81

- ☐ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☐ Operator, Past
☐ Other

CHRYSLER CHEMICAL DIVISION
Trenton , Michigan



- ```

1 Chemical Plant
2 Friction Material Plant
3 Piston Mfg. Plant
4 Tank Farm
5 Product Storage - Pads
6 Powerhouse
7 Parking Area
8 Rolling Oil Plant
9 Waste Treatment
10 Drum Storage Area
11 Drum Storage Area

```

LAND - 41 ACRES  
BUILDINGS - 350,000 SQ. FT.  
0' 50' 150' 300'  
SCALE

FACILITY DRAWING

JUN 10 1981

